



# CCP Annual Inspection Report

Brickhaven No. 2 Mine Tract A Structural Fill


DWM Permit 1910, DEMLR Permit 19-25

Charah, Inc.

*Moncure, North Carolina*

February 2023

Updated April 2023



This page intentionally left blank.

# Contents

Introduction .....	1
Inspection Report.....	1
Document Review.....	1
Permit Documents.....	1
Operational Documents.....	2
Visual Site Inspection.....	2
Structural Fill Access.....	2
Leachate Management.....	2
Stormwater Segregation and Erosion Control.....	3
Structural Fill Stability.....	3
Summary.....	3

## Appendices

Appendix A – Site Inspection Photographs

This page intentionally left blank.

# Introduction

This report summarizes the findings for the annual inspection conducted on January 17, 2023, of the Brickhaven No.2 Mine Tract "A" structural fill located off Moncure-Flatwood Road in Chatham County, North Carolina. The site is owned by Green Meadow, LLC and operated by Charah, Inc. under North Carolina Department of Environmental Quality (NCDEQ) Division of Waste Management (DWM) Structural Fill Permit 1910 issued June 5, 2015, in conjunction with the NCDEQ Division of Energy, Mineral and Land Resources (NCDEMLR) Mining Permit 19-25 also issued June 5, 2015. The Brickhaven No. 2 Mine Tract "A" structural fill project has been permitted and constructed in accordance with the North Carolina Coal Ash Management Act of 2014 (CAMA) and NCDEQ structural fill rules. The structural fill ceased receiving coal combustion products (CCP) on July 11, 2019, and it was capped with a composite liner system as approved by NCDEQ in the Closure Plan. A closure certification was submitted and approved by NCDEQ-DWM on April 7, 2021.

# Inspection Report

The goal of this inspection is to ensure the design, construction, and maintenance of the structural fill unit is consistent with recognized good engineering practices and a detailed level of engineering analysis is applied to evaluate existing conditions. This inspection includes the following.

- A discussion of the findings and remedies for any issues found in the document review.
- A discussion of the findings and remedies for any issues found in the site inspection.
- Any appearance of an actual or potential structural weakness of the CCP unit.
- Any existing conditions that are disrupting, or have the potential to disrupt, the operation and safety of the CCP unit.

The inspection report below discusses the document and visual inspection review.

## Document Review

HDR performed a cursory review of the available permit documents, as well as Charah's adherence to required recordkeeping. Operating Record documents include the following.

## Permit Documents

- NCDEQ structural fill permit and modification(s)
- NCDEQ mine permit and modification(s)
- Construction and Closure Certifications
- Erosion control permit and modification(s)
- Erosion control plans
- NPDES permit
- Leachate discharge permit
- Leachate pump and haul permit
- NCDEQ inspection reports

- Stormwater pollution prevention plan

## Operational Documents

- Operations plan
- Safety reports
- Groundwater reports
- Leachate collection and discharge records
- Leachate analysis reports
- Site inspection (weekly) reports
- Records/receipts for all (liner, leachate, and groundwater) system repairs
- Incident reports (safety, delivery of non-CCP materials, spills, etc.)

Weekly inspections were performed and documented by site personnel regarding operations, safety, maintenance of the groundwater wells, run-on and run-off controls, wind dispersal control systems, liner systems, and leachate collection systems. Where deficiencies were identified follow up corrective actions were also documented. Review of the above documents did not reveal any indications of operation or safety concerns regarding the CCP structural fill.

## Visual Site Inspection

A visual inspection, conducted on January 17, 2023, of the CCP structural fill was performed to identify signs of distress, malfunction, or threats to safety not identified in the document review or weekly inspection records. The weather during the site visit was sunny with an approximate temperature of 45 degrees Fahrenheit. This inspection was limited to the CCP structural fill, stormwater control devices and leachate systems. This does not address other site operational areas such as the rail unloading area.

The site inspection included an evaluation of the following site features.

1. Structural fill access
2. Leachate management system
3. Stormwater segregation and erosion control
4. Structural fill visual stability

## Structural Fill Access

Automobile access to the facility is from Moncure-Flatwood Road, which is controlled by a gate requiring check in and check out of visitors. CCP prior to closure arrived via railroad and was unloaded onto off-road dump trucks. This area was not reviewed as ash is no longer being received at the site. The site has a stone access road that wraps around the perimeter of the site. The structural fill has two access ramps, one in the northeast corner and the other in the southwest corner, which is connected by a gravel road across the top deck area.

## Leachate Management

The leachate management system for the structural fill includes a series of perforated High-Density Polyethylene (HDPE) pipes within the lined area that drain to either a sump in Cell 1 or a

sump in Cell 6. Both sums have two pumps installed to pump leachate to three onsite storage tanks. Site staff turned both sums on to pump to the tanks at the time of the inspection. At the initial site inspection, the Cell 1 sump panel reported leachate levels at 4.53 ft and the Cell 6 sump reported leachate levels at 6.40 feet. The pumps for both cells were fixed and documented to have the Cell 1 level to 0.95 ft and Cell 6 level to 11.2 inches on April 6, 2023.

The leachate enclosures and tanks exhibited no signs of leakage at the time of the inspection. The leachate tanks contained leachate and were actively being drained into tanker trucks for transportation to one of the approved disposal locations.

## **Stormwater Segregation and Erosion Control**

Charah converted Sediment Basins 1, 2 and 7 into stormwater retention ponds as directed by NCDEMLR for final reclamation. The other sediment basins were decommissioned and vegetated. The retention ponds that remained in place were observed to contain stormwater and function properly. Overall, the areas within the structural fill appeared to have adequate vegetation and showed no signs of structural concern. No signs of CCP release were observed.

## **Structural Fill Stability**

Based on the site inspection, no structural weaknesses were observed in the compacted CCP material.

## **Summary**

Site staff are performing and maintaining the permit documents and routine maintenance and monitoring reports as required. The Cell pumps have been repaired and are maintaining appropriate leachate levels.

HDR's review and visual inspection identified no apparent structural weakness in the CCP material placed as a part of the permanent structural fill.

This page intentionally left blank.

# A

## Appendix A – Site Inspection Photographs

This page intentionally left blank.



**Photo 1**



**Photo 2**



Photo 3




Photo 3a Cell 1 Level (April 6, 2023)



Photo 3b Cell 6 Level (April 6, 2023)



Photo 4



**Photo 5**



**Photo 6**



**Photo 7**



**Photo 8**



**Photo 9**



**Photo 10**



**Photo 11**



**Photo 12**

This page intentionally left blank.



440 S Church Street, Suite 1200  
Charlotte, NC 28202-2075  
704.338.6700  
NC License F0116

[hdrinc.com](http://hdrinc.com)

© 2023 HDR, Inc., all rights reserved